

表 3.4.8

承插铸铁管接口填料深度 (mm)

管 径	接 口 间 隙	承 口 总 深	接口填料深度			
			油麻、石棉水泥接口油麻、 膨胀水泥砂浆接口		油麻、铅接口	
			麻	灰	麻	铅
75	10	90	33	57	40	50
100	10	95	33	62	45	50
125	10	95	33	62	45	50
150	10	100	33	67	50	50
200	10	100	33	67	50	50
250	11	105	35	70	55	50
300	11	105	35	70	55	50
350	11	110	35	75	60	50
400	11	110	38	72	60	50
450	11	115	38	73	65	50
500	12	115	42	77	60	60
600	12	120	42	78	60	60
700	12	125	42	83	65	60
800	12	130	52	88	70	60
900	12	135	45	90	75	60
1000	13	140	45	95	71	69
1100	13	145	45	100	76	69
1200	13	150	50	100	81	69